






Windmill ■




1




4x Tech Brick 1x12




1x Baseplate




2




1x Plate 1x4




1x Motor



3



1xPlate 1x4




4




1x Pulley




1x Axle #6




1x Tech Brick 1x6




5




1x Rubber Band #16




6




2x Plate 1x4




7




1x Tech Brick 1x6




2x Tech Brick 1x8




8




2x Tech Brick 1x8




9




2x Tech Brick 1x6



10




4x Tech Brick 1x4




11



1x Bushing



1x Tech Brick 1x2




1x Tech Brick 1x4




1x Axle #6




1x Pulley




12




1x Tech Brick 1x2




1x Tech Brick 1x4




13




1x Gear 40 tooth





14




4x Tech Plate 2x8




Optional Step: Add IR Receiver for Remote Control







1x




2x




6x




4x



4x




4x




4x




2x




4x




1x



1x



1x



1x

6



2x



1x